

25-27 Green Street Banksmeadow 2019 Sydney NSW 2019, Australia P +61 2 9666 3788 F +61 2 9666 4805 E erapol@erapol.com.au

www.erapol.com.au

## PRODUCT TEST REPORT

Report Date: 07<sup>th</sup> July 2017 Pages: 2

Test Dates: 29-10-15 Testing Officer: Jose Diaz Sample Tested: Aptane P263/B900 Report No: WR58266

Low Density Buoyancy foam (Aptane P263/B900)

Product: Aptane P263/B900

Sample Identification: Low Density Buoyancy foams - Core density (47 kg/m³ and 56 kg/m³)

Test required: Stability under temperature recycling - (MSCD.8 (70)2.7.1)

Resistance to hydrostatic pressure (NSCV Part C Subsection 6B Annex F Clause F4)

Water absorption to 1.25m (MSC.8 (70) 2.7.5)

Hydrocarbon resistance test (NSCV Part C Section 6 Subsection 6B Annex F Table F2)

Test Conditions: Aging -10 cycles of [8h intervals at  $((+65^{\circ}C) - (RT) - (-30^{\circ}C))$ ]

Immersion in water (7days at Tf = 1.25m)

Compression @ 10% deformation at (23°C – 50%RH)

Hydrocarbon resistance – 30 days @ 38°C

Results:

**Immersion in water after aging** 

1111	Dry sample (Density 46.8 kg/m³)	Dry sample (Density 56.0 kg/m³)
Dry mass (g)	174.98	203.08
Mass after Immersion (g)	175.93	205.02
% mass change after immersion (%)	0.5	0.95

Compression @ 10% deformation

	Density (46.8) kg/m <sup>3</sup>	Density (56.0) kg/m³
Sample ID	Compression at 10% deformation (kPa)	Compression at 10% deformation (kPa)
S1 (kPa)	364.6	406.6
S2 (kPa)	345.3	432.2
S3 (kPa)	350.5	428.6
Average	353.5	422.5

Exposure to hydrocarbon vapour

	Dry sample (Density 46.8 kg/m³)	Dry sample (Density 56.0 kg/m³)
Dry mass (g)	171.00	190.24
Mass after Immersion (g)	169.76	189.01
% mass change after 30 day immersion (%)	0.73	0.65



NSW 2019, Australia

www.erapol.com.au

## Comments:

- The compressive strength of the foam in kPa at 10% strain shall not be less than the greater of 95Tf or 235 kPa (All the samples PASS)
- No deformations or shrinkage were observed during the stability under temperature recycling
- After the immersion in the water (7 days @ 1.25m) samples show no sign of damage such as shrinking, cracking, swelling, dissolution or change in mechanical properties
- No sign of damage or deterioration observed for hydrocarbon testing.

Jose Diaz	
Testing Officer	_

This document shall not be reproduced except in full. This product test report applies only to the sample tested. Unless otherwise stated, the sample and description are provided by the client."