

Kaiser LiquiDYE

TECHNICAL DATA SHEET

DESCRIPTION:

Kaiser LiquiDYE comes in a liquid form and is a colouring agent for candle wax. It has a low insertion temperature. The wax must be liquid and still clear. LiquiDYE gives a strong, brilliant, shiny colour. It has a good burning behaviour and good colour stability. Addition depends on the wax mixture and desired colour tone. Recommend dosage is 0.1% -0.2% (0.1%-0.4% for black). It will stain workbench and hands, we recommend wearing gloves, aprons and taking precautions when handling. LiquiDYE will stain. The burning behaviour is influenced by many facts and must be tested. Please refer to Safety Data Sheet before use. Available on request.

HEATING:

Low insertion temperature. Wax must be liquid and still clear.

INSTRUCTIONS:

Add to liquefied wax. Stir through until completely dissolved and incorporated. Short stirring is sufficient. Add fragrance if desired. Pour wax at its recommended pouring temperature.

TYPICAL PROPERTIES:

Blending temperature:	When wax is liquid
Agitation:	Short stirring time
Recommended dosage:	0.1%-0.2% (0.1%-0.4% for black)

NOTE:

Always keep in containers of same material as the original one. Keep in cool, dry place, avoid direct sunlight. Keep at temperature not exceeding 35°C. 12-month durable.